Gully Diesel Repair
PO Box 993662
Redding, CA 96099
9702503028
stgul@msn.com

INVOICE

BILL TO
Spalding Sanitation

INVOICE # 9409
DATE 09/10/2026
DUE DATE 10/10/2026
TERMS 30 Days

ITEM	DESCRIPTION	QTY	RATE	AMOUNT
Vehicle Details	Mahindra 3616 hst	1	0.00	0.00
Filter:A59	Air Filter	1	51.01	51.01T
Filter:F56	Fuel Filter	1	13.63	13.63T
Filter:O36	Oil Filter	1	7.67	7.67T
Filter:O94	Hydraulic Filter	1	23.81	23.81T
Filter:O95	Hydraulic Filter	1	81.49	81.49T
Relay:30A	12V 30A Relay	1	11.31	11.31T
Battery:MTP2	Group 78DT 12V Battery	1	239.18	239.18T
Battery Charge		1	2.00	2.00
MISC	Electrical Supplies	1	34.50	34.50T
Conduit:Hose:H4	Hydraulic Hose Per Foot	12	7.38	88.56T
Fitting:G-JF9	F JIC 37 Flare Swivel	2	18.55	37.10T
Fitting:G-PPM4	M O-Ring Boss Swivel	1	24.32	24.32T
Fitting:G-JF10	F JIC 37 Flare Swivel	2	15.62	31.24T
Stud:Stud	12" 1/4 Threaded stud	1	8.19	8.19T
Fluid:EO	Engine Oil Gallon	1.50	22.99	34.49T
Labor:Labor	9/1 7.0 9/4 5.0 Diag hyd leak. Found hydraulic line with hole rubbed through, made new line and install. Found two other lines that looked questionable, replaced those as well. Change oil and filters. Install new battery that fits and secure with battery hold down. Install new starter and test, machine clicks but does not turn over, check power to start post, only getting 6 volts. Install 12 volt relay. Top off hyd/trans fluid. Starts properly again. Check fluids. Blow out radiator. Good to go.	12	165.00	1,980.00

Credit card payments may be subject to a 3% surcharge.

I hereby authorize the repair work to be done along with necessary materials. You and your employees may operate the vehicle for purposes of testing, inspection and or delivery at my risk. An express mechanic's lien is acknowledged on the vehicle to secure the amount of repairs thereto. You will not be held responsible for loss or damage to vehicle or any articles left in vehicle in case of fire, that, accident or any other cause beyond your control.

x_____

SUBTOTAL	2,668.50
TAX	49.77
TOTAL	2,718.27
BALANCE DUE	**$2,718.27**

Credit card payments may be subject to a 3% surcharge.