

Sewer 1

From: STEPHEN GULLY <stgul@msn.com>
Sent: Thursday, July 23, 2026 6:31 AM
To: Sewer 1
Subject: Tractor clutch quote

QUOTE from Gully Diesel
Shop location
16198 Cloverdale Rd
Anderson ca 96007

Parts 1200
Sublet machine work 150
Labor 2800
Total 4150.00

Mahindra 3616 hst tractor

Quote to split tractor and replace clutch and clutch release bearing. New pilot bearing. Machine flywheel surface for new clutch plate. Having not seen or heard issue with tractor there may be other issues unknown.
Quote does not include freight, taxes, or any other ancillary parts needed.

May be able to haul tractor down to redding for a nominal fuel charge if timing coincides with a planned visit to Spalding VFD.

Stephen Gully
970-250-3028
Gully Diesel Repair

**Dave's Tractor, Inc.**

24015 Blackberry Ave.
Red Bluff, CA 96080
ph#: (530) 528-0755
fax #: (530) 528-8305
www.davestractor.com

Estimate

Date	Estimate #
7/9/2026	26990

Name / Address
Spalding Community Services District 502-907 Mahogany Way Susanville, CA 96130 Att: 825-3258

X	Description	Qty	Cost	Total
	Mahindra 3616 HST 4wd CAB SERIAL NUMBER: 36HX110670302			
	Throw bearing noise is getting worse. Split tractor, replace throw out bearing along with clutch assembly.	21	140.00	2,940.00
	10281111000 Pressure Plate		411.00	411.00T
	19641112000 Clutch Disc		338.00	338.00T
	11761015000 Throw Out Bearing		74.00	74.00T
	07500562054 Input Shaft Bearing (Have to remove this shaft to replace throw out bearing. 9/10 times this bearing needs to be replaced.		24.00	24.00T
	99940001510 Pilot Shaft Bearing		23.00	23.00T
	Shipping Inbound to Dave's Tractor		35.00	35.00
	Send flywheel to machine shop to get resurfaced.		175.00	175.00
	Hydraulic Tractor Transmission fluid, GL-4 per qt. (Will have to drain the hydraulic fluid to split the tractor to replace the clutch).	36	5.75	207.00T
	Anti-freeze price per qt. (The Cab has a heater core in which we will have to drain the coolant.)	6	4.90	29.40T
	Freon for the A/C		65.00	65.00T
	Hydraulic filter for Mahindra 3616 PN: 19642509000		60.00	60.00T
	HST filter for Mahindra 3616 PN: 19682581000		39.00	39.00T
	Hazardous Materials Charge		5.00	5.00

Sign Here X_____

Subtotal	\$4,425.40
Sales Tax (7.25%)	\$92.10
Total	\$4,517.50



18920 Nut Tree Lane
Anderson, CA 96007

Phone: 530-365-6343
Fax: 530-365-6474

e-mail: gullyequipment@yahoo.com
web: www.gullyequipment.com

Estimate

Date	Estimate #
7/22/26	895573 E

Name / Address
Spalding Community Sewer Brad Mallory

Make/Model	Serial No.	Other	
MAHINDRA	36HX110670302	3616HST	
Description	Qty	Cost	Total
ESTIMATE FROM DAVE'S TRACTOR - CUSTOMER TO PURCHASE PARTS DIRECT	1	1,004.00	1,004.00T
Labor	1	5,200.00	5,200.00
LABOR TO SEPARATE TRACTOR, REPLACE CLUTCH ASSEMBLY AND RELATED BEARINGS. CHANGE ALL FILTERS AND ENGINE OIL. CUSTOMER TO SUPPLY PARTS FROM DAVE'S TRACTOR ESTIMATE, FILTERS AND OIL.			
*GULLY EQUIPMENT REPAIR HAS NOT SEEN THIS MACHINE AND IS BASING ESTIMATE ON INFORMATION GIVEN BY BRAD MALLORY AND THE ESTIMATE FROM DAVE'S TRACTOR. PRICES SUBJECT TO CHANGE DEPENDING ON STATUS OF MACHINE ONCE IT IS IN SHOP.			
Please sign, date and e-mail to gullyequipment@yahoo.com this approved estimate.		Subtotal	\$6,204.00
		Sales Tax (7.75%)	\$77.81
		Total	\$6,281.81